

Materialvorratsliste

Federstahldraht (rund)

Werte in () = keine Normabmessung

Abmessung	D DH	VDSi Cr	4310 NS	4310 HS	4568
0,18	X		X		X
0,20	X		X		
0,22	X		X		
0,25	X		X		
0,28	X		X		
0,30	X		X		X
0,32	X		X		
0,33	X				
0,34	X				
(0,35)	X		X		X
0,36	X		X		X
0,38	X		X		
0,40	X		X	X	X
0,43	X		X		
0,45	X		X		X
0,48	X		X		X
0,50	X	X	X		X
0,53	X	X	X		X
0,55	X				
0,56	X	X	X		X
(0,58)	X				
0,60	X	X	X		X
0,63	X	X	X		X
0,65	X	X	X		X
(0,68)	X				
0,70	X	X	X		
0,75	X	X	X		
0,80	X	X	X	X	X
0,83	X				
0,85	X	X	X	X	X
0,90	X	X	X		X
0,95	X	X	X		X
1,00	X	X	X	X	X
1,05	X	X			X
1,10	X	X	X		X
1,20	X	X	X	X	X
1,25	X	X	X		X
1,30	X	X	X		X
1,40	X	X	X		X
1,50	X	X	X		X
1,60	X	X	X		X
1,70	X	X	X		X
1,80	X	X	X	X	X

Abmessung	D DH	VDSi Cr	4310 NS	4310 HS	4568
1,90	X	X	X		X
2,0	X	X	X		X
2,10	X	X	X	X	X
(2,20)	X	X			
2,25	X	X	X	X	
(2,30)	X	X			
2,40	X	X	X		X
2,50	X	X	X		X
2,60	X	X	X		
(2,70)	X	X			
2,80	X	X	X		
2,90		X			
3,0	X	X	X		
3,20	X	X	X		X
3,40	X	X	X		X
(3,50)	X	X	X		
3,60	X	X	X		X
(3,70)		X			
(3,80)	X	X			
4,0	X	X	X		
4,25	X	X	X		X
4,50	X	X	X		
(4,60)	X	X			
4,75	X	X	X		
5,0	X	X	X		X
5,30	X	X	X		X
5,50	X	X			
5,60	X	X	X		X
6,0	X	X			
6,30	X	X	X		X
6,5	X	X	X		
7,0	X	X	X		
7,5	X	X	X		X
8,0	X	X	X		
8,5	X	X	X		
9,0	X	X	X		
9,5	X	X			
10,0	X	X			
10,5	X				
11,0	X				
11,5	X				
12,0	X		X		